



info@perlagrp.com

2009 PRICE LIST

HELICOPTER MODEL

R44 Raven II with Standard Equipment

APPROX. WEIGHT (LBS) SUGGESTED RETAIL PRICE* \$US

1500 424,000

R44 Clipper II with Utility Floats

1548 455,000

R44 Clipper II with Pop-Out Floats

1566 461,000

OPTIONAL EQUIPMENT

Leather Seats

1.8 1,100

Pocket for Fire Extinguisher**

1 50

Fire Extinguisher, 14-oz (Fly Away Delivery Only)**

1 1 100

Forward Cabin Cover including all Windows

4.8 50 (Exchange)

Observation Bubble Window (each door)****

— 500

Air Conditioning

33.0 18,500

Xenon HID Landing Lights

1.0 900 (Exchange)

OPTIONAL INSTRUMENTS

Artificial Horizon**

2.5 3,990

Above Horizon w/Slip Skid Indicator**

2.5 4,150

Directional Gyro**

2.0 4,690

Turn Coordinator

1.2 1,000

Vertical Compass PAI-700 (replaces standard compass)

— No Charge (Exchange)

IVSI United Instruments (replaces standard VSI) .

— 5 980 (Exchange)

Digital Clock (replaces standard clock) —

— 180 (Exchange)

Millibar Altimeter (replaces standard in-Hg)

— No Charge

OPTIONAL AVIONICS

COM, King KY196A w/Nine Memory Channels, Cyclic Grip

Control Standard Standard Transponder, Garmin GTX327

w/Remote Mode C Altitude Encoder** Standard Standard

GPS/COM, Garmin 420W COM1 (replaces KY196A)

3.0 5,300 (Exchange)

GPS/COM/NAV Garmin 430W COM 1 w/ GI-106A

(replaces KY196A)

8.2 10,600 (Exchange)

GPS/COM/NAV Garmin 430W COM 1 w/ KCS55A HSI***

(replaces KY196A) 19.6 24,900 (Exchange)

Transponder, Garmin GTX328 Mode S w/Remote Mode C

Altitude Encoder**(replaces GTX327 Transponder)

1.1 1,400 (Exchange)

Transponder, Garmin GTX330 Mode S w/Remote Mode C

Altitude Encoder**

(replaces GTX327 Transponder, includes TIS)

1.1 2,630 (Exchange)

ELT, Kannad 406 AF Series 406 MHz

1.8 2,700

* Prices in US dollars and subject to change without notice.

** May be required for Part 135 Air Taxi Operation.

*** KCS55A is a slaved DG and CDI VOR LOC G/S Display. Not available on Clipper II w/ pop-out floats.

**** Note: Bubble windows reduce cruise speed by approximately 5 knots and may cause door seal leakage.

(OVER)

2009 ROBINSON R44 RAVEN II

RHC Oil Filter
Hydraulic Power Controls
Auxiliary Fuel System
RPM Throttle Governor
Cabin Heater & Defogger
Carbon Monoxide Detector
Removable Dual Controls
Throttle Correlator
Rotor Brake
Engine Oil Quick-Drain
Rate-of-Climb Indicator
Airspeed Indicator
Rotor & Engine Dual Tachometer
Sensitive Altimeter (in-Hg)
Manifold Pressure Gauge
King KY196A COM w/9 Mem Ch on Cyclic Grip
Garmin GTX327 Transponder w/Mode C Alt Encoder
Intercom System with VOX, NAT AA83
(Stereo & Music Compatible)
Floor & Hand Intercom Switches
Clock (Quartz)
Magnetic Compass
Digital OAT Gauge
Hourmeter
Cylinder Head Temp Gauge
Oil Temp & Pressure Gauges
Ammeter
Door Opener, Gas Spring, All Four Doors
Tinted Windshield & Door Windows*
Form-Fitted Fabric Seats
Inertia Reel Shoulder Harness
Adjustable Pedals on Pilot Side
Carpeting and Acoustic Interior
Muffler and Soundproofing
Baggage Compartments
Door Locks
Hard Point on Belly
Low Voltage Light
Low Oil Pressure Light
Low Fuel Light
Low Rotor RPM Light & Horn
Main Gear Box Temp Light
Main Gear Box Chip Light
Tail Gear Box Chip Light
Rotor Brake Engaged Light
Starter Engaged Light
Engine Fire Light
Dual Landing Lights
Navigation, Panel, Rear Seat, & Map Lights
Anti-Collision Light
Tow-Cart Adapter
Ground Handling Wheels
Windshield Cover
Custom Fabric Travel Bag
Rotor Blade Tie-Downs

STANDARD EQUIPMENT INCLUDES